

MATERIAL SAFETY DATA SHEET

MSDS NO. : DPO-003  
DATE: 06/01/1992  
PAGE: 1 of 3

MINOLTA CORPORATION  
101 WILLIAMS DRIVE  
RANSEY, NJ 07446

EMERGENCY TEL. NO. CONTACT YOUR REGIONAL POISON  
CONTROL CENTER  
INFORMATION TEL. NO. 201-825-4000

SECTION 1 - PRODUCT IDENTIFICATION

PRODUCT : PHOTOCONDUCTOR      EQUIPMENT NO. EP2120, EP2121, EP2151, EP4230, EP4300, EP4301,  
EP4320, EP4321, EP5400, EP5401, EP5320, EP5420

SECTION 2 - PRODUCT AND COMPONENT HAZARD DATA

INGREDIENT	CAS NO.	OSHA PEL-TWA	ACGIH TLV-TWA	
Aluminum drum		N.AP.	N.AP.	>97 %
Binder resin		N.AP.	N.AP.	< 1 %
Photosensitive material		N.AP.	N.AP.	< 1 %
Pigment		N.AP.	N.AP.	< 1 %

HMIS RATING : HEALTH : 0      FLAMMABILITY : 1      REACTIVITY : 1

SECTION 3 - EMERGENCY AND FIRST AID

INHALATION : No treatment is required.  
INGESTION : No treatment is required.  
EYES : No treatment is required.  
SKIN : No treatment is required.

PRIMARY ROUTE OF ENTRY : Not possible.

SYMPTOMS OF OVEREXPOSURE  
ACUTE : None.

CHRONIC : None.